

Date: Wednesday, 1/11/2006 4:19:09 PM  
 User: Kim Johnston

## Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services		Drawing Name	: BASKET BASE ASSEMBLY (350)		
Job Number	: 25439A			Part Number	: D2221	
Estimate Number	: 10189			Drawing Number	: D2221 REV F	
P.O. Number	: N/A			Project Number	: N/A	
This Issue	: 1/11/2006		S.O. No. : N/A	Drawing Revision	: F	
Prsh Rev.	: NC			Material	: N/A	
First Issue	: N/A			Due Date	: 1/30/2006	
Previous Run	: 25438A			Qty:	1	Um: Each
Written By	: SEE COMMENT BELOW					
Checked & Approved By	: SEE COMMENT BELOW					
Comment	: Est Rev:J 05.09.02 Added D3442-1KJ/JLM					

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :	
1.0	D31661	Basket Hoop	
		Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)	
		Pick:	
		Qty Part Number Description Batch	
		4 D3166-1 RIB B24880	
2.0	D22323	Basket Hinge	
		Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)	
		Pick:	
		Qty Part Number Description Batch	
		2 D2232-3 Hinge bracket B24527	
3.0	D2325	Support Gusset (350 Bask)	
		Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)	
		Pick:	
		Qty Part Number Description Batch	
		4 D2325 Support Gusset B24529	
4.0	D23273	Spacer Bushing	
		Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)	
		Pick:	
		Qty Part Number Description Batch	
		2 D2327-3 Bushing B24530	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/11/2006 4:19:09 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET BASE ASSEMBLY (350)

Job Number: 25439A

Part Number: D2221

Job Number:



Seq. #: Machine Or Operation:

Description :

5.0 D2581 Mounting Bracket



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
2	D2581	Mounting Bracket	<u>B25189</u>

*Mo/01/24*

6.0 D34421 Shim



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
2	D3442-1	Shim	<u>B23544</u>

*Mo/01/24*

7.0 M304EX07516F Expanded Metal Flat Stai



Comment: Qty.: 37.8000 sf(s)/Unit Total : 37.8000 sf(s)

Pick:

Qty	Part Number	Description	Batch
36 sf	M304EX0.75-16F	Expanded Metal	<u>M19149</u>

*Mo/01/25*

8.0 M304TS0750W065 304 SQ Tube.75x.75x.065W



Comment: Qty.: 29.4000 f(s)/Unit Total : 29.4000 f(s)

Pick:

28' 3/4" x 3/4" x 0.063 wall 304/316 SStubing  
Batch: M19447

*Mo/01/23*

9.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235

2-Drill hole in D2221-3 as per Dwg D2221

3-Deburr

4-Remove all markings on material before welding

5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required

*Mo/01/25*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes  No  DQA:  Date: 06/01/07  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/11/2006 4:19:09 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET BASE ASSEMBLY (350)

Job Number: 25439A

Part Number: D2221

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

10.0	QC9/6	DDIMENSIONAL & WELDING INSPECTION
------	-------	-----------------------------------



Comment: DDIMENSIONAL & WELDING INSPECTION

PD 06-01-25

11.0	POWDER COATING	POWDER COATING
------	----------------	----------------



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

ML 06-01-26

12.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
------	-----	---



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

ML 06/01/26

13.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
------	-----------------	----------------------------



Comment: HAND FINISHING RESOURCE #1

Seal support gusset seam with white sikaflex-291 Batch: M19597

Expiry date: 06-18-06

ML 06/01/27

14.0	DC	DOCUMENT CONTROL
------	----	------------------



Comment: DOCUMENT CONTROL

Inspection Level 21

ML 06/01/27

Job Completion



U 06-01-27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




DESIGN BW	DRAWN BY PH	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[initials]</i>	APPROVED <i>[initials]</i>	DRAWING NO. D2221	REV. F SHEET 1 OF 3
DATE 05.06.07	TITLE BASKET BASE ASSEMBLY (350)		SCALE NTS
C	95.11.21	SEPARATE BASKET AND LID	
D	96.06.21	CHANGE LATCH	
E	01.04.19	CHANGE HINGE	
F	05.06.07	ADD SHIM UNDER HINGES, ADD HOLES FOR SPLIT LID BASKETS	

RELEASED

05.08.19 *[initials]*

PARTS LIST FOR D2221 BASKET BASE ASSEMBLY

PART NO	QUANTITY	LENGTH A	LENGTH B	DESCRIPTION
D2221-1	2	—	96.00	RIB
D2221-3	2	—	25.50	RIB
D2221-5	2	18.88	—	RIB
D2221-7	1	55.25	—	RIB
D2232-3	2	N/A	N/A	HINGE PLATE
D2235-1	4	N/A	N/A	RIB
D2325	4	N/A	N/A	SUPPORT GUSSET
D2327-3	2	N/A	N/A	BUSHING
D2581	2	N/A	N/A	MTG BRKT
D3442-1	2	N/A	N/A	SHIM




SHOP COPY

RETURN TO  
ENGINEERING



UNCONTROLLED COPY

SUBJ. TO AMENDMENT  
OR FIGHT NOTICE



45° WORK ORDER


NO. 25439A

D2221-1/-3/-5/-7

- 1) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST
- 2) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.060 WALL SQUARE TUBING (REF. DART SPEC M304TS0.750W.060)
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) DRILL Ø0.257 HOLES ONLY WHEN ASSEMBLING D2221 BASE WITH D2989-041/-043 BASKET LID

Copyright © 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.




DESIGN BW	DRAWN BY PH	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2221
DATE 05.06.07	TITLE BASKET BASE ASSEMBLY (350)	REV. F SHEET 2 OF 3 SCALE 1:20

WORK ORDER  
NO. 234394

D2221 BASKET BASE ASSEMBLY


- 1) MESH MATERIAL: 3/4-16F EXPANDED SS (REF DART SPEC M304EX0.75-16F)
- 2) WELD PER DART QSI 004
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) FINISH: POWDER COAT ENTIRE ASSEMBLY WHITE (4.3.5.2) PER DART QSI 005 4.3

SHOP COPY  
RELEASED  
RETURN BIG INNEE  
D2325 TO MENDMENT  
SUBMIT YOUR NOTICE







DESIGN BW	DRAWN BY PH	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>MM</i>	APPROVED <i>MM</i>	DRAWING NO. D2221	REV. F SHEET 3 OF 3
DATE 05.06.07		TITLE BASKET BASE ASSEMBLY (350)	SCALE 1:8



SECTION A-A SAME BOTH END RIBS



SECTION B-B SAME BOTH CENTER RIBS

SHOP COPY  
RETURN TO  
ENGINEERING  
RELEASED COPY  
05-08-19 *MM* ENDMENT  
NO. 25439A  
WORK ORDER  
NO. 25439A

